




Schwartzwalder Daily Summary Report



Report Date:	7/3/2025	Lead Operator:	Patrick D
		Assistant Operator(s):	Bryant A

Effluent Discharged:	0.281 Mgal	MW-18 Level:	161.3 ft
Average Flowrate:	203.5 gpm	Transducer Level:	265.0 ft
Effluent to Date:	4.314 Mgal		



Finished Water Quality			
Parameters	Temp	pH	Cond
Values	21°C	8.04	187 µS/cm

Chemical Inventory			
Chemicals	Antiscalant	NaOH	BaCl
Vol. Used	2 Gal	14 Gal	2 Gal
Vol. Remaining	381 Gal	171 Gal	50 Gal
Vol. Staged	0 Gal	140 Gal	150 Gal
Days Available	191 Days	22 Days	100 Days

Safety Issues/Concerns:

- N/A

Notes:

- Item B29 Completed. Repaired PVC Leak on IX Vessel #3.



Schwartzwalder Daily Summary Report 7/3/25

1 message

Bryant Acevedo <bryant.acevedo@linkan.com>

Fri, Jul 4, 2025 at 10:33 AM

To: Peter Hays - DNR <peter.hays@state.co.us>

Cc: Adam Billin <Adam.Billin@linkan.com>, Sam Billin <sam.billin@linkan.com>, Quinn Westmoreland <quinn.westmoreland@linkan.com>, Brandy Wadford <brandy.wadford@linkan.com>, Jared Buck <jared.buck@linkan.com>, Chris Prosper <chris.prosper@linkan.com>, Alex Schwiebert <alex.schwiebert@linkan.com>, Patrick Delaney <pdelaney@blackfoxmining.com>

Good morning,

See attached for 7/3/25 Summary Report and Pictures of

- Item B29 work completed.

Best,

Bryant Acevedo
Operator Technician




cell: 720-238-6169

linkan.com • bryant.acevedo@linkan.com

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.


5 attachments



IMG_7873.jpeg
2818K



IMG_7874.jpeg
2919K



IMG_7875.jpeg
2563K



IMG_7876.jpeg
2634K



SWTP Daily Summary Report 7.3.25.pdf
237K







VESSEL
3



WWW.KINET.CO