

Shell Frontier Oil & Gas Inc.
Annual Report - CDRMS Prospecting Notice of Intent (NOI)

Report Year: 2024 NOI Anniversary Date: August 19, 2003
 NOI Number: P-2003-018 Prospecting Project Name: 2003 Public Land Consolidated NOI

| PROSPECTOR INFORMATION | SURFACE LANDOWNER INFORMATION |
|---|--------------------------------------|
| Prospector: Shell Frontier Oil & Gas Inc. (SFOGI) | Landowner: Bureau of Land Management |
| Address: Woodcreek, E676-B | Address: White River Field Office |
| 150-C North Dairy Ashford | 220 East Market Street |
| Houston, TX 77079 | Meeker, CO 81641 |
| Telephone: 832-337-7230 | Telephone: 970-878-3800 |
| Fax: None | |
| Contact Person: Samantha Baker | |
| email: Samantha.d.baker@shell.com | |

| DESCRIPTION OF ACTIVITIES <small>All UTM Coordinates are NAD 1983, Z12</small> | | | | | |
|--|----------------|------------------|-----------------|---|--|
| Pad 10-6 - BLM portion of access road only (see P-2003-022 for pad and non-BLM portion of access road) | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| Pad 10-6 BLM access road | na - road only | na - road only | na - road only | 12/2007 (borehole P&A completed) | P&A work completed on single installed hole and surface casing cut off below final grade. Site reseeded 2004 (phase 2 interim reclamation) and again in 2010 (final reclamation phase); some vegetation established on pad. Minor occurrence of Houndstongue along portions of access road in 2013. Noxious weed monitoring. CO DRMS inspected and stated that the pad had meant reclamation standard and approved for release |
| Is site in final reclamation? | | | | Yes | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | Yes (details provided on attached site map) | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |

| Pad 56-16-199 (B1-16) | | | | | |
|--|-----------|------------------|-----------------|-----------------------------------|---|
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 56-16-199 (B1-16-L5) | Hydrology | 4426814.871 | 712940.421 | 09/2002 (borehole P&A completed) | All installed holes (2) P&A'd. Pad regraded and reseeded in 2003 (phase 2 interim reclamation); 100 ft x 20 ft x 3 ft depression installed for water sampling activities. Depression & other portions of pad redisturbed in 2010 for remaining P&A work regraded, soil material replaced, and site reseeded Fall 2010 (final reclamation phase). Weed control (spring/fall Downy Brome spraying event) and Noxious weed monitoring 2012 thru 2021, spring spray only. DRMS/BLM approved final reclamation release of pad in 2021. |
| 56-16-199 (B1-16-L3) | Hydrology | 4426804.099 | 712913.605 | 2010 (borehole P&A completed) | |
| Is site in final reclamation? | | | | Released | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |

| Pad 57-15-199 (B2-15) | | | | | |
|--|-----------|------------------|-----------------|-------------------------------------|---|
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 57-15-199-A (B2-15) | Hydrology | 4426607.113 | 714492.458 | P&A, reclaimed & reseeded Fall 2014 | Soil stockpile reseeded 03/2004. Pad downsized 06/2009 and reseeded 10/2009 (phase 2 interim reclamation). Pit closed. P&A work for all installed holes completed in 2014 & surface casing cut off below final grade. Pad regrading, soil replacement and reseeded work completed in Fall 2014 (final reclamation phase). Ground cover with 80% vegetation cover with multiple vegetation (or species developed with seed heads), 15% shrubs at 6" - 18". Noxious & annual weed control ongoing from 2012-2020. DRMS/BLM approved final reclamation release of pad in 2020. |
| 57-15-199-BG | Hydrology | 4426617.743 | 714472.782 | P&A, reclaimed & reseeded Fall 2014 | |
| 57-15-199-L5 (B2-15) | Hydrology | 4426566.035 | 714484.764 | P&A, reclaimed & reseeded Fall 2014 | |
| 57-15-199-L4U | Hydrology | 4426603.015 | 714478.483 | P&A, reclaimed & reseeded Fall 2014 | |
| 57-15-199-L4L | Hydrology | 4426588.949 | 714484.375 | P&A, reclaimed & reseeded Fall 2014 | |
| Is site in final reclamation? | | | | Released | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |

| Pad 58-14-199 (B3-14) | | | | | |
|--|------------------|------------------|-----------------|---|--|
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 58-14-199 (B3-14-L4) | Hydrology / Core | 4426962.070 | 716600.120 | 12/2003 (borehole P&A completed) | Single installed borehole P&A'd. Pit closed, pad and access road recontoured and reseeded 03/2004 (phase 2 interim reclamation). 80% vegetation cover with multiple vegetation (or species developed with seed heads). 2019 - small depression reclaimed, reseed area and access road. Continuous monitoring of noxious & annual weed control from 2012-2022. Continue to monitor for overgrazing from Wild horses in the area and re-seed where required. The access rd and pad has established vegetation but has been grazed. wildhorse |
| Is site in final reclamation? | | | | Yes | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | Yes (details provided on attached site map) | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |

| Pad 60-21-199 (B4-21) | | | | | |
|--|-----------|------------------|-----------------|--|--|
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 60-21-199-UT | Hydrology | 4424580.740 | 712173.609 | P&A, reclaimed & reseeded Fall 2014 | Soil stockpile reseeded 03/2004 (phase 2 interim reclamation). Pad downsized 07/2009, reseeded 10/2009 (phase 2 interim reclamation). Pit closed. P&A work for all installed holes completed in 2014 & surface casing cut off below final grade. Pad regrading, soil replacement & reseeded work completed in Fall 2014 (final reclamation phase). Ground cover 80% vegetation cover with multiple vegetation (or species developed with seed heads), 20% shrubs at 6" - 18". Noxious & annual weed control ongoing from 2012-2020. DRMS/BLM |
| 60-21-199-A (B4-21) | Hydrology | 4424530.058 | 712210.894 | P&A, reclaimed & reseeded Fall 2014 | |
| 60-21-199-BG | Hydrology | 4424570.969 | 712161.389 | 9/2007 borehole P&A completed; reclaimed & reseeded Fall 2015 | |
| 60-21-199-L5 (B4-21) | Hydrology | 4424569.131 | 712188.395 | P&A, reclaimed & reseeded Fall 2015 | |
| 60-21-199-BR | Hydrology | 4424555.806 | 712162.510 | P&A, reclaimed & reseeded Fall 2015 | |
| 60-21-199-L4U | Hydrology | 4424564.936 | 712174.692 | P&A, reclaimed & reseeded Fall 2015 | |
| 60-21-199-L4L | Hydrology | 4424558.895 | 712188.716 | 5/2008 (borehole P&A completed; reclaimed & reseeded Fall 2015 | |
| 60-21-199-L3 | Hydrology | 4424552.886 | 712202.808 | 5/2009 borehole P&A completed; reclaimed & reseeded Fall 2015 | |
| Is site in final reclamation? | | | | Yes | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | Yes (details provided on attached site map) | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |

| | | | | | | |
|--|-----------|------------------|-----------------|-------------------------------------|----------|--|
| Is site in final reclamation? | | | | | Released | approved final reclamation release of pad in 2020. |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | | NA | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | | None | |
| Pad 61-22-199 (B5-22) | | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 61-22-199 (B5-22-L1) | Hydrology | 4424689.107 | 714505.042 | 12/13/2007 (borehole P&A completed) | | Pit closed, pad & access road recontoured & reseeded in 2004 (phase 2 interim reclamation). Site rebuilt in anticipation of drilling MZ well. Did not drill; site again re-contoured & reseeded with access road 09/2008. Minor occurrence of cheat grass in 2012 and 2013 (est. 2% of site) Noxious & annual weed control ongoing from 2012-2020. Ongoing noxious weed monitoring. DRMS/BLM approved final reclamation release of pad in 2020. |
| Is site in final reclamation? | | | | | Released | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | | NA | |
| Provide a description of any new prospecting activity occurring during the preceding year: | | | | | None | |

| Pad 62-23-199 (B6-23) | | | | | |
|--|-----------|------------------|-----------------|--|---|
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 62-23-199-A (B6-23-A) | Hydrology | 4425340.511 | 716584.272 | 10/17/2014 (borehole P&A completed) | Soil stockpile reseeded 03/2004, pit closed 09/2008. Pad downsized and reseeded 09/2009 (phase 2 interim reclamation). Weed control work completed in 2012 and 2013. Minor occurrence of cheat grass in 2013 (est. 2% of site). 2014- P&A work for all installed holes and surface casing cut off below final grade. Pad regrading, soil replacement & reseeding work completed in Fall 2014 (final reclamation phase). Good ground cover to protect growth & seeding. Access road has good ground cover from reseed in 2015, 60% ground cover. 2018-2019 Pad 80% vegetation cover with multiple vegetation (or species developed with seed heads), 15% shrubs at 6" - 18". 2022, focus on spg/fall treatment of Downy Brome and Russia Thistle. 2023- Amendments added woody chips, organic compost and area has been reseeded. On going Noxious weed monitoring 2012 thru 2024. |
| 62-23-199 (B6-23-L5) | Hydrology | 4425381.852 | 716587.670 | 6/26/2008 (borehole P&A completed) | |
| 62-23-199 (B6-23-L4) | Hydrology | 4425372.567 | 716613.270 | 10/17/2014 (borehole P&A completed) | |
| Is site in final reclamation? | | | | Yes | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA (no spraying required - minor occurrence) | |
| Provide a description of any new prospecting activity occurring during the preceding year: | | | | None | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Pad 64-28-199 (B7-28) | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 64-28-199 (B7-28-A(U)) | Hydrology | 4423035.080 | 712157.360 | 6/26/2008 (borehole P&A completed) | Soil stockpiles reseeded. Pit closed. Pad downsized 07/2009, reseeded 10/2009 (phase 2 interim reclamation). Access road and portions of pad redistributed during 2010 P&A work regraded and soil material replaced 2010. Pad and access road reseeded Fall 2010. Final reclamation areas have fair to good establishment of seeded grasses. No weed infestations observed. Noxious & annual weed control ongoing from 2012-2020, spring spray only. DRMS approved final reclamation release of pad in 2020. 2022, focus on spg/fall treatment of Downy Brome and Russia Thistle. |
| 64-28-199-BG | Hydrology | 4423051.913 | 712164.182 | 10/7/2010 (borehole P&A completed) | |
| 64-28-199-L5 | Hydrology | 4423057.284 | 712178.102 | 10/7/2010 (borehole P&A completed) | |
| 64-28-199-L4L | Hydrology | 4423067.856 | 712206.829 | 10/7/2010 (borehole P&A completed) | |
| 64-28-199-L4U | Hydrology | 4423062.660 | 712192.460 | 10/7/2010 (borehole P&A completed) | |
| | | | | | |
| Is site in final reclamation? | | | | Released | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |
| | | | | | |
| Pad 65-27-199 (B8-27) | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 65-27-199 (B8-27-L1) | Hydrology | 4423523.760 | 714496.880 | 09/2003 (borehole P&A completed) | Pad and access road recontoured & reseeded in 2004 (Final reclamation). Pit closed. No weed infestations observed. Noxious & annual weed control ongoing from 2012-2020, spring spray only. DRMS approved final reclamation release of pad in 2020. |
| Is site in final reclamation? | | | | Released | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |
| | | | | | |
| Pad 66-26-199 (B9-26) | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 66-26-199-B | Hydrology | 4423791.994 | 716142.561 | 10/17/2014 (borehole P&A completed) | Soil stockpile reseeded 03/2004. Pad downsized 11/2009 (phase 2 interim reclamation). Pit closed. P&A work for all installed holes completed in 2014 and surface casing cut off below final grade. Pad regrading, soil replacement and reseeding work completed in Fall 2014 (final reclamation phase). Good ground cover to protect growth & seeding. Ground cover with 80% vegetation cover with multiple vegetation (or species developed with seed heads), 15% shrubs at 6" - 18". Access road has good ground cover from re-seed in 2015 (60%). Note: it appears that someone has been driving partially up the access road but not to the pad. 202 - focus on spg/fall treatment of Downy Brome, 2023- Amendments added woody chips, organic compost and area has been reseeded. On going Noxious weed monitoring 2012 thru 2024. |
| 66-26-199-L5 | Hydrology | 4423779.309 | 716134.109 | 09/2010 (borehole P&A completed) | |
| 66-26-199-L3 | Hydrology | 4423753.188 | 716132.996 | 09/2010 (borehole P&A completed) | |
| 66-26-199-L4(L1) (B9-26-L1) | Hydrology | 4423774.350 | 716160.020 | 10/17/2014 (borehole P&A completed) | |
| | | | | | |
| | | | | | |
| Is site in final reclamation? | | | | Yes | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | Yes (details provided on attached site map) | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| | | | | | |
|--|------------------|-------------|------------|-------------------------------------|---|
| 2-2-299-BG | Core / Hydrology | 4421066.752 | 716478.362 | 09/29/2014 (borehole P&A completed) | Completed in 2014 & surface casing cut off below final grade. Pad regrading, soil replacement & reseeding work completed in Fall 2014 (final reclamation phase). Access road has good ground cover from re-seed in 2015, 60% ground cover. Ground cover with straw at 50%, 95% Pad vegetation cover with multiple vegetation (or species developed with seed heads), 15% shrubs at 6" - 24". Weed control (spring/fall Downy Brome spraying event) and Noxious weed monitoring 2012 thru 2019, spring spray only. DRMS approved final reclamation release of pad in 2019. |
| 2-2-299-L5 | Core / Hydrology | 4421066.187 | 716493.642 | 09/29/2014 (borehole P&A completed) | |
| 2-2-299-L4 | Core / Hydrology | 4421052.930 | 716500.893 | 09/29/2014 (borehole P&A completed) | |
| 2-2-299-L4U | Core / Hydrology | 4421053.337 | 716485.594 | 11/2006 (borehole P&A completed) | |
| 2-2-299-L1 | Core / Hydrology | 4421080.713 | 716521.691 | 05/2007 (borehole P&A completed) | |
| 2-2-299-L3 | Core / Hydrology | 4421035.416 | 716509.722 | 09/29/2014 (borehole P&A completed) | |
| 2-2-299-UTL | Core / Hydrology | 4421067.148 | 716447.660 | 09/29/2014 (borehole P&A completed) | |
| Is site in final reclamation? | | | | Released | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |

| Pad 3-1-299 | | | | | | |
|--|------------------|------------------|-----------------|---|--|--|
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES | |
| 3-1-299-C | Core | 4420601.796 | 718370.729 | 11/2003 (borehole P&A completed) | Pit closed, soil stockpiles and portion of site reseeded for groundcover 09/2008 (phase 2 interim reclamation). Access road has good ground cover, 60% ground cover and vegetation regrowth. Good ground cover, Pad 95% vegetation cover with multiple vegetation (or species developed with seed heads), 15% shrubs at 6" - 24". Weed control (spring/fall Downy Brome spraying event) and Noxious weed monitoring 2012 thru 2019, spring spray only. DRMS approved final reclamation release of pad in 2019. | |
| 3-1-299-UTU | Core / Hydrology | 4420599.122 | 718355.763 | 09/2015 (borehole P&A completed) | | |
| 3-1-299-UTL | Core / Hydrology | 4420621.626 | 718405.708 | 09/2015 (borehole P&A completed) | | |
| 3-1-299-AG | Core / Hydrology | 4420613.421 | 718360.875 | 09/2015 (borehole P&A completed) | | |
| 3-1-299-BG | Core / Hydrology | 4420616.318 | 718375.696 | 09/2015 (borehole P&A completed) | | |
| 3-1-299-L5 | Core / Hydrology | 4420618.853 | 718390.773 | 09/2015 (borehole P&A completed) | | |
| 3-1-299-L4 | Core / Hydrology | 4420607.327 | 718400.739 | 09/2015 (borehole P&A completed) | | |
| 3-1-299-L3 | Core / Hydrology | 4420604.522 | 718385.696 | 09/2015 (borehole P&A completed) | | |
| Is site in final reclamation? | | | | Released | | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | | |
| Pad 4-1-299 | | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES | |
| 4-1-299-L3(H) | Core/Hydrology | 4420282.622 | 717211.100 | 03/2007 (borehole P&A completed) | Pit closed. Soil stockpiles reseeded 08/2008 (phase 2 interim reclamation). Reclaimed area around pad and pit spoil area has good establishment of seeded grasses. P&A work for all installed holes completed in 2014 and surface casing cut off below final grade. Pad regrading, soil replacement and reseeding work completed in Fall 2014 (final reclamation phase). Good ground cover with 95% vegetation cover with multiple vegetation (or species developed with seed heads), 20% shrubs at 6" - 24". Weed control (spring/fall Downy Brome spraying event) and Noxious weed monitoring 2012 thru 2019. 2019- DRMS & BLM approved final release of Pad 4. | |
| 4-1-299-A | Hydrology | 4420293.170 | 717201.575 | 10/13/2014 (borehole P&A completed) | | |
| 4-1-299-B | Hydrology | 4420296.896 | 717216.558 | 10/13/2014 (borehole P&A completed) | | |
| 4-1-299-L5 | Hydrology | 4420300.933 | 717231.018 | 10/13/2014 (borehole P&A completed) | | |
| 4-1-299-L4 | Hydrology | 4420289.905 | 717241.930 | 10/13/2014 (borehole P&A completed) | | |
| 4-1-299-L3 (UT) | Hydrology | 4420286.153 | 717227.141 | 10/13/2014 (borehole P&A completed) | | |
| Is site in final reclamation? | | | | Released | | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | | |
| Pad 5-18-298 | | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES | |
| 5-18-298-C | Core | 4416464.008 | 720195.652 | 05/2004 (borehole P&A completed) | Pad downsized, some soil material respreads, and entire site reseeded 09/2007 (phase 2 interim reclamation). Portion of soil stockpile not respreads was reseeded and curlex applied. P&A work for all installed holes completed in 2015 & surface casing cut off below final grade. Pad regrading, soil replacement and reseeding work completed in Fall 2015 (final reclamation phase). Weed control & good ground cover to protect growth & seeding. 2017/2018 - Below average rainfall throughout the summer and fall months. 2019 - above avg. rainfall, multiple weed control events, focus on Downy Brome, spot re-seeding 2020 - spot re-seeding and weed control during dry conditions. 2021 -Dry conditions will wait to re-seed in 2022, recieved good Fall moisture - late rain events. 2023- Amendments added were woody chips, organic compost and area has been reseeded. 2024: observed 40% growth, reseeded areas of concern, semi dry conditions. On going Noxious weed monitoring 2012 thru 2024. | |
| 5-18-298-UT | Hydrology | 4416485.466 | 720216.823 | 10/2015 (borehole P&A completed) | | |
| 5-18-298-AG | Hydrology | 4416470.971 | 720220.690 | 10/2015 (borehole P&A completed) | | |
| 5-18-298-BG | Hydrology | 4416460.119 | 720209.991 | 10/2015 (borehole P&A completed) | | |
| 5-18-298-L5 | Hydrology | 4416449.334 | 720199.076 | 10/2015 (borehole P&A completed) | | |
| 5-18-298-L4 | Hydrology | 4416452.214 | 720184.160 | 11/2007 (borehole P&A completed) | | |
| 5-18-298-L3 | Core / Hydrology | 4416474.916 | 720205.978 | 10/2015 (borehole P&A completed) | | |
| Is site in final reclamation? | | | | Yes | | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | Yes (details provided on attached site map) | | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | | |
| Pad 6-13-299 | | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES | |
| 6-13-299-C | Core | 4417600.444 | 717920.880 | 01/2004 (borehole P&A completed) | Pit closed, soil stockpiles reseeded, and portion of pad reseeded for groundcover 09/2008 (phase 2 interim reclamation). P&A work for all installed holes completed in 2015 & surface casing cut off below final grade. Pad regrading, soil replacement and reseeding work completed in Fall 2015 (final reclamation phase). Weed control (spring/fall Downy Brome spraying event) and Noxious weed monitoring 2012 thru 2021. Access road has good ground cover, and vegetation regrowth. Pad Ground cover 70% vegetation cover with multiple vegetation, Fenced installed for grazing management. 2020 - heavy grazing, established vegetation it is short, inspector wants to see 4" to 6" in height. Weed control (spring/fall Downy Brome spraying event) and Noxious weed monitoring 2012 thru 2021. 2021 - DRMS/BLM approved final release of the pad per regulatory standards. | |
| 6-13-299-UTU | Core / Hydrology | 4417591.464 | 717909.459 | 9/2015 (borehole P&A completed) | | |
| 6-13-299-UTL | Core / Hydrology | 4417578.992 | 717909.383 | 9/2015 (borehole P&A completed) | | |
| 6-13-299-AG | Core / Hydrology | 4417621.830 | 717908.706 | 9/2015 (borehole P&A completed) | | |
| 6-13-299-BG | Core / Hydrology | 4417606.443 | 717908.865 | 9/2015 (borehole P&A completed) | | |
| 6-13-299-L5 | Core / Hydrology | 4417614.655 | 717921.865 | 9/2015 (borehole P&A completed) | | |
| 6-13-299-L5R | Core / Hydrology | 4417636.797 | 717908.584 | 9/2015 (borehole P&A completed) | | |
| 6-13-299-L4 | Core / Hydrology | 4417629.957 | 717921.697 | 9/2015 (borehole P&A completed) | | |
| 6-13-299-L3 | Core / Hydrology | 4417583.876 | 717922.686 | 09/2005 (borehole P&A completed) | | |
| Is site in final reclamation? | | | | Released | | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | | |
| Pad 7-18-298 | | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES | |
| 7-18-298-C | Core | 4417984.531 | 719943.823 | 02/2004 (borehole P&A completed) | Pit closed, soil stockpiles reseeded, pad downsized and partially reseeded for groundcover 11/2007 (phase 2 interim reclamation). P&A work for all installed holes completed in 2015 & surface casing cut off below final grade. Pad regrading, soil replacement and reseeding work completed in Fall 2015 (final reclamation phase). Weed control (spring/fall Downy Brome spraying event) and Noxious weed monitoring 2012 thru 2021. 2021 - DRMS/BLM approved final release of the pad per regulatory standards. | |
| 7-18-298-UTU | Hydrology | 4417971.495 | 719917.561 | P&A, reclaimed & reseeded Fall 2015 | | |
| 7-18-298-UTL | Core / Hydrology | 4417980.551 | 719905.258 | P&A, reclaimed & reseeded Fall 2015 | | |
| 7-18-298-AG | Hydrology | 4417986.625 | 719919.255 | P&A, reclaimed & reseeded Fall 2015 | | |
| 7-18-298-BG | Hydrology | 4417992.718 | 719933.463 | 11/2006 (borehole P&A completed) | | |
| 7-18-298-L5 | Hydrology | 4417998.688 | 719947.361 | P&A, reclaimed & reseeded Fall 2015 | | |
| 7-18-298-L4 | Hydrology | 4417989.802 | 719959.494 | P&A, reclaimed & reseeded Fall 2015 | | |
| 7-18-298-L3 | Hydrology | 4417977.658 | 719931.653 | P&A, reclaimed & reseeded Fall 2015 | | |

| | | | | | | |
|--|-----------|------------------|-----------------|-------------------------------------|---|--|
| Is site in final reclamation? | | | | | Released | and Noxious weed monitoring 2012 thru 2018. Good ground cover 80% vegetation cover with multiple vegetation (or species developed with seed heads), 20% shrubs at 6" - 18". Weed control (spring/fall Downy Brome spraying event) and Noxious weed monitoring 2012 thru 2020, spring spray only. DRMS approved final reclamation release of pad in 2020. |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | | NA | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | | None | |
| Pad 8-3-298 | | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES | |
| 8-3-298-C | Core | 4421045.171 | 723390.672 | P&A, reclaimed & reseeded Fall 2015 | Pit closed, pad downsized, some soil material respread, and site reseeded 09/2007 (phase 2 interim reclamation). Portion of soil stockpile not respread was reseeded and curlex applied. P&A work for all installed holes completed in 2015 & surface casing cut off below final grade. Pad regrading, soil replacement and reseeded work completed in Fall 2015 (final reclamation phase). Weed control(spring/fall Downy Brome and annual weeds spraying event) and Noxious weed monitoring 2012 thru 2020. 2020- pad partial re-seeded where the weed control had stressed the vegetation. 2017/2018 - Below average rainfall throughout the summer and fall months. 2019 - above avg. rainfall, multiple weed control events, focus on Downy Brome, spot re-seeding 2020 - spot re-seeding and weed control during dry conditions. 2021 -Dry conditions will wait to re-seed. 2022- reseeded partial pad, recieved Fall rain for good moisture. 2023- Amendments added woody chips, organic compost and area has been reseeded. 2024: observed 40% growth, reseeded areas of concern, semi dry conditions. On going Noxious weed monitoring 2012 thru 2024. | |
| 8-3-298-UT | Hydrology | 4421054.026 | 723406.457 | P&A, reclaimed & reseeded Fall 2015 | | |
| 8-3-298-AG | Hydrology | 4421038.373 | 723407.867 | P&A, reclaimed & reseeded Fall 2015 | | |
| 8-3-298-BG | Hydrology | 4421029.959 | 723395.047 | P&A, reclaimed & reseeded Fall 2015 | | |
| 8-3-298-L5 | Hydrology | 4421021.688 | 723382.687 | P&A, reclaimed & reseeded Fall 2015 | | |
| 8-3-298-L4 | Hydrology | 4421027.987 | 723368.570 | P&A, reclaimed & reseeded Fall 2015 | | |
| Is site in final reclamation? | | | | | Yes | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | | Yes (details provided on attached site map) | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | | None | |

| Pad 9-9-298 | | | | | |
|--|------------------|------------------|-----------------|--|--|
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 9-9-298-C | Core | 4418663.904 | 722732.411 | 01/2004 (borehole P&A completed) | Pad downsized, some soil material respread, and site reseeded 09/2007 (phase 2 interim reclamation). Portion of soil stockpile not respread was reseeded and curlex applied. P&A work for all installed holes completed in 2015 & surface casing cut off below final grade. Pad regrading, soil replacement and reseeded work completed in Fall 2015 (final reclamation phase). Re-seeded in fall of 2016 with straw mulch crimped. Perimeter fence installed fall of 2016, protections from livestock in area. 2017/2018 - Below average rainfall throughout the summer and fall months. 2019 - above avg. rainfall, multiple weed control events, focus on Downy Brome, spot re-seeding 2020 - spot re-seeding and weed control during dry conditions. 2021 - Dry conditions will wait to re-seed. 2022- reseeded partial pad, recieved Fall rain for good moisture. 2023- Amendments added woody chips, organic compost and area has been reseeded. 2024: observed 30% growth, reseeded areas of concern, semi dry conditions. On going Noxious weed monitoring 2012 thru 2024. |
| 9-9-298-UT | Hydrology | 4418671.516 | 722748.371 | Reclaimed & seeded 2015; re-seed pad and installed perimeter | |
| 9-9-298-AG | Hydrology | 4418671.516 | 722748.371 | Reclaimed & seeded 2015; re-seed pad and installed perimeter | |
| 9-9-298-BG | Hydrology | 4418648.480 | 722736.396 | Reclaimed & seeded 2015; re-seed pad and installed perimeter | |
| 9-9-298-L5 | Hydrology | 4418640.158 | 722723.504 | Reclaimed & seeded 2015; re-seed pad and installed perimeter | |
| 9-9-298-L4 | Hydrology | 4418655.065 | 722722.390 | Reclaimed & seeded 2015; re-seed pad and installed perimeter | |
| Is site in final reclamation? | | | | Yes | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | Yes (details provided on attached site map) | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |
| | | | | | |
| Pad 10-32-198 | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 10-32-198-H | Core | 4422362.875 | 721490.201 | 04/2004 (borehole P&A completed) | Pit closed, pad downsized, some soil material respread, and entire site reseeded 09/2007 (phase 2 interim reclamation). Remainder of soil stockpile reseeded and curlex applied. P&A work for all installed holes completed in 2015 & surface casing cut off below final grade. Pad regrading, soil replacement and reseeded work completed in Fall 2015 (final reclamation phase). 2017/2018 - Below average rainfall throughout the summer and fall months. 2019 - above avg. rainfall, multiple weed control events, focus on Downy Brome, spot re-seeding 2020 - spot re-seeding and weed control during dry conditions. 2021 - Dry conditions will wait to re-seed. 2022- reseeded partial pad, recieved Fall rain for good moisture. 2023- Amendments added woody chips, organic compost and area has been reseeded. 2024: observed 30% growth, reseeded areas of concern, semi dry conditions. On going Noxious weed monitoring 2012 thru 2024. |
| 10-32-198-UT | Hydrology | 4422348.746 | 721488.275 | P&A, reclaimed & reseeded Fall 2015 | |
| 10-32-198-AG | Hydrology | 4422359.785 | 721478.095 | P&A, reclaimed & reseeded Fall 2015 | |
| 10-32-198-BG | Hydrology | 4422374.482 | 721482.551 | P&A, reclaimed & reseeded Fall 2015 | |
| 10-32-198-L5 | Hydrology | 4422389.173 | 721486.983 | P&A, reclaimed & reseeded Fall 2015 | |
| 10-32-198-L4 | Core / Hydrology | 4422377.942 | 721497.252 | P&A, reclaimed & reseeded Fall 2015 | |
| Is site in final reclamation? | | | | Yes | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | Yes (details provided on attached site map) | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |
| | | | | | |
| Pad 11-16-298 (subsequent additional holes included in NOI #P-2005-001) | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 11-16-298-C | Core | 4415770.543 | 722406.772 | 05/2004 (borehole P&A completed) | Pit closed 10/2008, soil stockpiles reseeded (phase 2 interim reclamation). P&A work for all installed holes completed in 2015 & surface casing cut off below final grade. Pad regrading, soil replacement and reseeded work completed in Fall 2015 (final reclamation phase). Weed control (spring/fall Downy Brome spraying event) and Noxious weed monitoring 2012 thru 2020, spring spray only. DRMS approved final reclamation release of pad in 2020. |
| 11-16-298-UT | Hydrology | 4416852.827 | 722351.559 | 10/2015 (borehole P&A completed) | |
| 11-16-298-AG | Hydrology | 4416865.495 | 722342.825 | 10/2015 (borehole P&A completed) | |
| 11-16-298-BG | Hydrology | 4416879.265 | 722350.168 | 11/2006 (borehole P&A completed) | |
| 11-16-298-L5 | Hydrology | 4416892.928 | 722357.243 | 10/2015 (borehole P&A completed) | |
| 11-16-298-L4 | Hydrology | 4416879.777 | 722365.364 | 10/2015 (borehole P&A completed) | |
| 11-16-298-L3 | Hydrology | 4416866.191 | 722358.572 | 10/2015 (borehole P&A completed) | |
| Is site in final reclamation? | | | | Released | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |
| | | | | | |
| Pad 12-22-298 | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 12-22-298-C | Core | 4416006.404 | 724730.640 | 03/2004 (borehole P&A completed) | Soil stockpiles reseeded, pit closed 10/2008 (phase 2 interim reclamation). Pad constructed on existing well site. Pad and road regraded, soil material replaced, and disturbed areas reseeded in 2010 (final reclamation phase). Weed control (spring/fall Downy Brome spraying event) and Noxious weed monitoring 2012 thru 2020, spring spray only. DRMS approved final reclamation release of pad in 2020. |
| 12-22-298UT-X | Core / Hydrology | 4416032.952 | 724727.263 | 08/2009 (borehole P&A completed) | |
| 12-22-298-BG | Hydrology | 4416021.783 | 724737.760 | 10/2006 (borehole P&A completed) | |
| 12-22-298-B-X | Core / Hydrology | 4416007.375 | 724735.172 | 08/2009 (borehole P&A completed) | |
| 12-22-298-L5-X | Core / Hydrology | 4415992.824 | 724728.887 | 08/2009 (borehole P&A completed) | |
| 12-22-298-L5 | Core / Hydrology | 4416021.819 | 724737.766 | 10/2006 (borehole P&A completed) | |
| 12-22-298-L4 | Core / Hydrology | 4416003.768 | 724718.438 | 10/2006 (borehole P&A completed) | |
| 12-22-298-L4-X | Core / Hydrology | 4415990.492 | 724714.340 | 08/2009 (borehole P&A completed) | |
| Is site in final reclamation? | | | | Released | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |
| | | | | | |
| Pad 13-14-298 (subsequent additional holes included in NOI #P-2005-001) | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| 13-14-298-C | Core | 4417352.839 | 725873.171 | 04/2004 (borehole P&A completed) | Soil stockpiles reseeded following pad construction. All installed holes P&A'd. Vegetation and woody plants established on SE portion of pad (part of old J.M. Huber pad). Remaining portion of pad & road regraded and soil material replaced, reseeded completed Fall 2010 (final reclamation phase). 2020- pad partial re-seeded where the weed control had |
| 13-14-298-BG | Core / Hydrology | 4417329.458 | 725896.927 | 08/2009 (borehole P&A completed) | |
| 13-14-298-L5 | Core / Hydrology | 4417339.435 | 725872.358 | 08/2009 (borehole P&A completed) | |
| 13-14-298-L4 | Core / Hydrology | 4417351.475 | 725862.622 | 08/2009 (borehole P&A completed) | |
| Is site in final reclamation? | | | | Released | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | NA | |
| Describe any new prospecting activity that occurred during the preceding year (from anniversary date): | | | | None | |

| | | | | | <p>stressed the vegetation. 2021 - Dry conditions, managed weeds around well stick-up and hand broadcast. Weed control and Noxious weed monitoring 2012 thru 2023. Good ground cover on access road and pad, continue with spring/fall brownie Brome monitor and control (will control on road edge). 2022- reseeded partial pad- areas around the wellhead. 2023 - spring/Fall weed treatment, annual inspection by the DRMS stated that it would be a candidate for final reclamation release in 2024.</p> |
|--|----------------|------------------|-----------------|---|--|
| Airplane Ridge Road (portion on BLM land) | | | | | |
| HOLE / WELL NAME / NO. | TYPE | UTM NORTHING (m) | UTM EASTING (m) | DATE OF LAST PROSPECTING ACTIVITY | RECLAMATION & WEED MANAGEMENT ACTIVITIES |
| Airplane Ridge Road | na - road only | na - road only | na - road only | Road active throughout the year | <p>Phase 1 interim reclamation completed during initial construction, Phase 2 interim reclamation completed as necessary as part of ongoing road maintenance. Weed control completed in 2012-20228. Noxious weed monitoring. The BLM COC has been closed and transferred to Mahogany Energy Corp. 2023: DRMS/BLM conducted annual site inspection and declared the Airplane Ridge road acceptable for reclamation standards, final release granted.</p> |
| Is site in final reclamation? | | | | No | |
| Is weed control being conducted in accordance with an approved weed management plan? | | | | Yes (details provided on attached site map) | |
| Provide a description of any new prospecting activity occurring during the preceding year: | | | | Periodic use throughout the year | |
| BOUNDARY OF AFFECTED AREA CLEARLY MARKED? | | | | | |
| Yes - Edge of disturbed areas is visible and follows affected area boundaries. | | | | | |
| DATE PROSPECTING ACTIVITY HAS ENDED OR WILL END | | | | | |
| Date: December 31, 2017 | | | | | |

| | | | |
|--|--|--------------------------------------|---|
| ACREAGES | | | |
| Number of acres currently affected: | 12.26 | | |
| Number of acres newly affected during current report year: | 0.00 | | |
| Number of acres reclaimed during current report year: | 0.00 | | |
| Estimated no. new acres to be affected in next report year: | 0.00 | | |
| Estimated no. new acres to be reclaimed in next report year: | 0.00 | | |
| Total acres in various stages of reclamation, since permitted prospecting activities began: | | | |
| Total acres backfilled: | 21.49 | Total acres regraded: | 21.49 |
| Total acres with topsoil replaced: | 21.49 | Topsoil replacement depth: | 3" to 6" range |
| Total acres seeded with approved mix: | 21.48 | Seed application method: | Drill seeded with small amounts of broadcast @ double |
| Total acres fertilized with approved fertilizer: | 14.96 | Fertilizer application method: | Broadcasted |
| Total acres mulched with approved mulch: | 21.48 | Mulch application method: | Straw Crimped |
| | | Mulch application rate: | 2 tons/acre |
| TOPSOIL MANAGEMENT | | | |
| Is adequate topsoil reserved for reclamation, based on the approved NOI? | NA for reclaimed sites (soil replacement completed) | | |
| Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? | NA for reclaimed sites (stockpiled soil replaced) | | |
| OFFICE OF STATE ENGINEER (OSE) | | | |
| If prospecting has exposed ground water, is the site in compliance with the approved NOI and the requirements of the Office of the State Engineer (OSE)? | NA (no groundwater exposed during prospecting) | | |
| HAZARDOUS MATERIALS | | | |
| Are all hazardous materials stored within approved spill containment structures? | NA for inactive and reclaimed sites (no hazmats on site) | | |
| MONITORING INFORMATION | | | |
| Does the NOI reclamation plan or Environmental Protection Plan (EPP) require that monitoring information be submitted annually? | No | If so, please attach to this report. | |
| FINANCIAL WARRANTY | | | |
| Bond instrument: | Travelers Casualty & Surety Company of America Statewide Prospecting Bond No. 104806644 | | |
| Current bond amount: | See attached Financial Warranty Cost Summary for current estimated reclamation cost. | | |
| UPDATED MAPS | | | |
| Location map: | See attached site map entitled "Location Map - 2003 Public Land Consolidated NOI" for the location of drill pads and acces roads included in this NOI. | | |
| Site maps: | See attached drill pad maps for location of drill holes, drill pad & access road disturbances, reclamation areas, and weed management details. | | |
| ABANDONMENT REPORTS | | | |
| Have Abandonment Reports been submitted in accordance with Rule 5.7? | Yes (submitted to DRMS in separate correspondence) | | |
| SIGNATURE / DATE | | | |
| Prospector: | Samantha Baker, Program Manager | | Date: 19-Aug-25 |