

Notes:

4K Equipment LLC. took over this permit on January 2, 2024. Material was removed for testing and to prepare reserve estimates.

9. Mining started north of the backfill area this year and disturbed 11.5 acres..

10. 6.0 acres in the new mining area has been temporarily sloped 4h to 1v to leave stable slopes until mining resumes.

13. Of the 6.4 acres that has been backfilled 5.7 of the area was backfilled during the last Bijou Creek highwater event in 2023.

15. As noted in the Mining and Reclamation Plans there is no topsoil to salvage from the mining area.

19. The bond was evaluated by the Division in December 2023 as a part of the permit transfer and found to be adequate to complete reclamation.

22. Please refer to the 2025 Annual Report Map for location of the areas of disturbance in the mine.