



MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: C & D Farms No. 2	MINE/PROSPECTING ID#: M-1999-043	MINERAL: Sand and gravel	COUNTY: Lincoln
INSPECTION TYPE: Monitoring	WEATHER: Clear	INSP. DATE: September 17, 2025	INSP. TIME: 11:30
OPERATOR: Lincoln County	OPERATOR REPRESENTATIVE: Ty Stogsdill	TYPE OF OPERATION: 110c - Construction Limited Impact	
REASON FOR INSPECTION: Normal I&E Program	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$0.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
INSPECTOR(S): Ben Hammar	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: September 26, 2025	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>NA</u>	(RD) ROADS----- <u>NA</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>NA</u>
(PW) PROCESSING WASTE/TAILING---- <u>NA</u>	(SF) PROCESSING FACILITIES----- <u>NA</u>	(TS) TOPSOIL----- <u>NA</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>NA</u>	(RV) REVEGETATION---- <u>NA</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>NA</u>	(RS) RECL PLAN/COMP-- <u>NA</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>NA</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>NA</u>
(AT) ACID OR TOXIC MATERIALS----- <u>NA</u>	(OD) OFF-SITE DAMAGE----- <u>NA</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This inspection was conducted by Ben Hammar as part of the Division's standard monitoring program. Ty Stogsdill and a representative from Lincoln County Road and Bridge were present as representatives of Lincoln County. The C&D Farms Pit No. 2 is located approximately 3.5 miles east of Arriba and is a 110c sand and gravel operation located in a perennial streambed. At the time of inspection the weather was clear and the ground was saturated due to significant local rainfall the previous day.

The annual report for this site is due yearly on April 5th and is currently up to date. Per the provided annual report, this site does not currently operate more than 180 days a year but is not currently listed as intermittent. Following a review of previous permitting actions, intermittent status has been requested for this site so no problem will be cited. Please be sure to indicate the site is intermittently used in future annual reports.

No issues with the hydrologic balance were observed. Standing water was present in the Arikaree River, but a significant amount of rainfall had occurred the day before this inspection. Ponded water was observed throughout Lincoln County on the day of inspection and so this does not appear to be a consistent issue.

All markers and signs were present and in reasonable condition. No evidence of outside disturbance or sedimentation was observed, and no deviations from the approved mine plan were found. As this is a county government site, no bond is held. No other issues were found.

Inspection Contact Address

Ty Stogsdill
Lincoln County
P.O. Box 39
Hugo, CO 80821

Enclosure

CC:

PHOTOGRAPHS



Photo 1: Posted mine ID sign. Lettering was legible in situ.



Photo 2: Primary site disturbance and standing water from rainfall.



Photo 3: Sand stockpile and surrounding area. Site boundary marker can be seen center left.