

Hernandez, Alysha

From: Musick, Jason
Sent: Wednesday, October 05, 2011 12:06 PM
To: Hernandez, Alysha
Subject: FW: Twentymile Coal, LLC - NOV CV-2011005 Abatement
Attachments: Field Report - Ross Pit 093011.pdf; IMG_0933.JPG; IMG_0934.JPG; IMG_0935.JPG

From: Nettleton, Jerry [<mailto:JNettleton@peabodyenergy.com>]
Sent: Wednesday, October 05, 2011 11:41 AM
To: Musick, Jason
Cc: Davis, E. Jason; Berdine, Mike; Wallace, Dave; Long, Dave L
Subject: Twentymile Coal, LLC - NOV CV-2011005 Abatement

Jason –

Attached is a field report and photos (provided as two separate e-mails due to size) from our Friday, September 30th inspection of the ongoing abatement activities, for the above-referenced NOV. Work is proceeding well, with ongoing processing of the waste materials to segregate them into the specific size/material categories identified in our original (09/28) inspection report. No haulage of the segregated products had occurred as of the reference inspection date.

We currently anticipate that processing of the material should be completed by October 11th. We also anticipate beginning haulage of the segregated waste products sometime next week, and will provide additional reports as we proceed.

Please feel free to contact me with any questions –

Best regards,

Jerry

Jerry M. Nettleton
Environmental Manager
Twentymile Coal, LLC
29515 RCR27
Oak Creek, Colorado 80467
970.870.2712
jnettleton@peabodyenergy.com



E-mail Disclaimer: The information contained in this e-mail, and in any accompanying documents, may constitute confidential and/or legally privileged information. The information is intended only for use by the designated recipient. If you are not the intended recipient (or responsible for the delivery of the message to the intended recipient), you are hereby notified that any dissemination, distribution, copying, or other use of, or taking of any action in reliance on this e-mail is strictly prohibited. If you have received this email communication in error, please notify the sender immediately and delete the message from your system.

TWENTYMILE COAL, LLC FIELD REPORT

Date: 9/30/2011

Location: Ross Pit

Conditions: SUNNY WARM

TC Personnel: Brian Watterson

Persons Contacted: Brandon Bower

Purpose of Field Visit: Check on segregation progress.

Field Notes: 3 metals/debris piles
fine, medium, and a number of coarse coal pile.

Main Coal Stockpile somewhat wet. Bower using
front end loader to move pile in order to speed up
drying it out.











