Hernandez, Alysha

From: Musick, Jason

Sent: Thursday, October 13, 2011 10:46 AM

To: Hernandez, Alysha

Subject: FW: FW: Twentymile Coal, LLC - NOV CV-2011005 Abatement **Attachments:** Field Report - Ross Pit 101211.pdf; IMG_0046.JPG; IMG_0047.JPG

From: Nettleton, Jerry [mailto:JNettleton@peabodyenergy.com]

Sent: Thursday, October 13, 2011 10:40 AM

To: Musick, Jason

Cc: Davis, E. Jason; Berdine, Mike; Wallace, Dave; Long, Dave L

Subject: RE: FW: Twentymile Coal, LLC - NOV CV-2011005 Abatement

Jason -

Attached is a field report and photos (sent as three e-mails due to size) from our Wednesday, October 12th final inspection of the completed abatement activities, for the above-referenced NOV. The following summarizes the current status of the NOV abatement activities:

- All waste material has been removed from Deakin's Pit and transported to Twentymile, and the prior stockpile area has been cleaned-up to bare soil
- Bower has completed processing and segregation of the waste materials at the Ross Pit, and has transported all
 of the fines (No. 4 product, as identified in 09/28 Report) to Twentymile for placement and disposal in the Coal
 Refuse Disposal Area
- All of the intermediate coally material (Nos. 2 and 3 products) has also been transported to Twentymile, where
 it has been windrowed adjacent to the Run-of-Mine Coal Stockpile, and incorporated into the Washplant feed,
 after being inspected for any debris
- Bower has completed removal and segregation of all debris (ie: wood, metal, cable and hose, concrete block, etc.) from the coarse reject material from the initial grizzly, has loaded and transported all coal and rock from the coarse product to Twentymile, and was completing loading of the final truckload of debris at the time of the inspection for transport to the Twin Landfill
- Cleanup of the previous stockpile areas and the area under and around the screening plant had been completed down to bare soil

Based on our site observations, and the information provided in this report, the final abatement step was completed today, and the sites (Deakins and Ross Pits) are ready for the CDRMS's verification inspection. Based on our subsequent phone conversation, the final verification inspection is scheduled for 1:00PM on Wednesday, October 19th -

Best regards,

Jerry

Jerry M. Nettleton Environmental Manager Twentymile Coal, LLC 29515 RCR27 Oak Creek, Colorado 80467



E-mail Disclaimer: The information contained in this e-mail, and in any accompanying documents, may constitute confidential and/or legally privileged information. The information is intended only for use by the designated recipient. If you are not the intended recipient (or responsible for the delivery of the message to the intended recipient), you are hereby notified that any dissemination, distribution, copying, or other use of, or taking of any action in reliance on this e-mail is strictly prohibited. If you have received this email communication in error, please notify the sender immediately and delete the message from your system.

TWENTYMILE COAL, LLC FIELD REPORT

Date: 10/12/11 2:30/M
Location: Source Bess (Sess (Ses Cook, Deep Conditions: Sunny (Link Cook, Deep
Conditions: Suns Classe Cook, Des
TC Personnel: - Juney Stande-Ton
Persons Contacted:
Purpose of Field Visit: final site visit to verity & placement Completion of weste processing seffection, removal. and clean-up activities
Field Notes: Sased on previous field inspections all waste processing and begregation had been campleted by Tuesdad (10/10), and most of the segregated problems had been removed from the site and transported to the designated disposal beations (Twenty mile or Tarin landsfill)
At the time of this inspection, fixuer fixus complaces were loading segregated trash materials (wood steel block capte etc.) into final truck for transport to Twin land till
5. Te cleanun hach heen completed down to







