

RECEIVED

JUL 09 2012

GRAND JUNCTION FIELD OFFICE
DIVISION OF
RECLAMATION MINING & SAFETY

To: Dustin Czapla, DRMS

From: Matt Welte

RE: Mine Inspection 6/5/12 of Permit # M-1987-074

Date: 7/6/12

Dear Mr. Czapla,

Please find the enclosed pictures of the permit boundary markers and mine identification sign for permit # M-1987-074. The permit boundary markers were in place as shown in the pictures. The mine identification sign had been knocked down by someone as the mine is accessed through a public BLM road. It has been put back up as shown in the picture. Please let me know if you have any further questions or if this needs any further attention.

Sincerely,



Matt Welte

Mayne Block and Stone

719-542-8278

CORNER #1





CORNER #2

CORNER #2



CORNER #3



m-87-074

CORNER #3

CORNER #4



CORNER #4

m-87-074



MINE ID SIGN

DOTS-RO
QUARRY
COLORADO
MINE LAND
claim # 187-074

