

Charles R. Ponchak
Consulting Geologist
15292 6050 Rd
Montrose, CO. 81403
Hm 970-249-2081 Wk 970-249-4434

November 29, 2012

DRMS - Durango Field Office
691 CR 233, Room A-2
Attn: Bob Oswald
Durango, CO. 81301

RE: Ruby Trust Mine, Permit M-1979-181, Corrective Action
of Problem, inspection date 10/1/12.

Dear Bob,


Attached you will find a series of photographs taken of
the covering of the Ruby Trust Mine low grade ore pile
covering. The tarps used are heavy weight Neoprene used
sign tarps which are UV resistant. The painted sign side
of the tarps is the most durable side and will with stand
the severe weather conditions encountered at the mine site.
The tarps should last several years.

If you have any questions or need additional information
please feel free to contact me.

Sincerely,



Charles R. Ponchak for
Walker Ruby Mining Company, Inc.





Ruby Trust Mine low grade ore stockpile covering



Ruby Trust Mine low grade ore stockpile covering



Ruby Trust Mine low grade ore stockpile covering



Ruby Trust Mine low grade ore stockpile covering



Ruby Trust Mine low grade ore stockpile covering