




COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY COAL PROGRAM INSPECTION REPORT



PERMIT INFORMATION

Permit Number: C-1980-001 Mine Name: Edna Strip Mine Operator: Chevron Mining, Inc. Operator Address: Mr. Ian Robb Chevron Environmental Management Company 6101 Bollinger Canyon Road, Room 5390 San Ramon, CA 94583	County: Routt Operation Type: Surface Permit Status: Permanent Cessation Ownership: Federal
	Operator Representative Present: None
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: February 21, 2013 Inspection Start Time: 09:00 Inspection End Date: Inspection End Time:	Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Snowing
Joint Inspection Agency: None	Joint Inspection Contacts:
Post Inspection Agency: None	Post Inspection Contacts:
Inspector(s): Robert D. Zuber	Inspector's Signature:  Signature Date: 2/22/2013

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection

N - Availability of Records

N - Backfill & Grading

N - Excess Spoil and Dev. Waste

NA - Explosives

N - Fish & Wildlife

N - Hydrologic Balance

N - Gen. Compliance With Mine Plan

N - Other

NA - Processing Waste

N - Roads

N - Reclamation Success

N - Revegetation

NA - Subsidence

N - Slides and Other Damage

N - Support Facilities On-site

R - Signs and Markers

NA - Support Facilities Not On-site

NA - Special Categories Of Mining

N - Topsoil

COMMENTS

During the inspection it was snowing. The ground was 100% covered with snow, up to three feet in some areas.

At the east entrance (from the Oak Creek valley and Highway 131), access to the mine site was not possible by vehicle. Access was made by snowshoe to the ridge at the north side of the site, but very little could be observed due to the snow.

The gate for the access road was open.

SIGNS AND MARKERS – Rule 4.02:

The entrance sign at the east entrance was observed and found to be in compliance.

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were taken as a result of this inspection, and none are pending.

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 2

PHOTOGRAPHS



The entrance sign at the east entrance (off Highway 131)



West Ridge is in background (not visible due to snow)

Number of Partial Inspection this Fiscal Year: 6

Number of Complete Inspections this Fiscal Year: 2