

COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY COAL PROGRAM INSPECTION REPORT



PERMIT INFORMATION

Permit Number: C-2010-088 Mine Name: Fruita Loadout Operator: CAM-Colorado, LLC Operator Address: Mr. Corey Heaps 2352 N 7th Street, Unit C Grand Junction, CO 81501	County: Mesa Operation Type: Loadout Permit Status: Temporary Cessation Ownership: Private Operator Representative Present: None	
Operator Representative Signature: (Field Issuan	ace Only)	

INSPECTION INFORMATION

Inspection Start Date: August 22. Inspection Start Time: 15:00 Inspection End Date: August 22, Inspection End Time: 15:30		In	spection Type: Coal Complete Inspection spection Reason: Normal I&E Program eather: Cloudy	
Joint Inspection Agency:		Joint Inspection Contacts:		
None				
Post Inspection Agency:		Post Inspection Contacts:		
None				
Inspector(s):	Inspector	r's Signati	ure: Signature Date:	
Michael P. Boulay	Michae	P. Bow	lay 8/28/13	

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

NA - Air Resource Protection NA - Roads

Y - Availability of Records NA - Reclamation Success

NA - Backfill & Grading
NA - Excess Spoil and Dev. Waste
NA - Subsidence

NA - Explosives
NA - Slides and Other Damage
Y - Fish & Wildlife
NA - Support Facilities On-site

Y - Hydrologic Balance Y - Signs and Markers

NA - Gen. Compliance With Mine Plan

NA - Support Facilities Not On-site

NA - Special Categories Of Mining

NA - Processing Waste NA - Topsoil

COMMENTS

This was a complete inspection of the Fruita Loadout conducted by Mike Boulay of the Division of Reclamation, Mining and Safety on August 22, 2013. There was no operator/representative from CAM Colorado, LLC present during the inspection. Weather conditions were overcast and warm. Ground conditions were dry.

OTHER (SPECIFY):

The Fruita Loadout is currently inactive and is in temporary cessation. The permit was issued on March 6, 2012 but the operator has not yet begun construction of any of the planned facilities. There was no activity at the site during this inspection and the site remains undisturbed by the loadout operations.

SIGNS AND MARKERS - Rule 4.02:

The Mine and Permit identification sign is properly displayed and maintained at the permit boundary.

DOCUMENTS RECEIVED None

OTHER (SPECIFY)

Number of <u>Partial</u> Inspection this Fiscal Year: 0 Number of <u>Complete</u> Inspections this Fiscal Year: 1

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were taken as a result of this inspection, and none are pending.

AVAILABILITY OF RECORDS

PERMIT RECORDS		HYDROLOGIC RECORDS	
DRMS Permit	X exp. 3/6/17	NPDES Permit	NA
Permit Application w/Revisions	X	NPDES Records	NA
Findings Document	X	Stormwater Management Plan	X
Insurance Certificate	X	SPCC Plan	NA
Bond Document	X	MSHA Pond Inspections	NA
Phased Bond Release	NA		NA
Documents/Findings		State Engineer's Pond Inspection	
Air Emission Permits	X	Quarterly Pond Inspections	NA
County Special Use Permits	X	Annual Hydrology Reports	NA
UG Mining Landowner Notification	NA	 Ground Water Monitoring 	NA
Subsidence Monitoring Reports	NA	 Surface Water Monitoring 	NA
Subsidence Monitoring Data	NA	 Spring & Seep Monitoring 	NA
Rill & Gully Survey	NA	Mine Water Discharge Monitoring	NA
Vegetation Monitoring Data	X	Mine Inflow Study	NA
Specific Variance Approvals	NA	Water Consumption Records	NA
Annual Reclamation Reports	NA	Well Permits	NA
Midterm Review Documents	NA		
DRMS/OSM Inspection	X		
Reports/Enforcement Actions (3			
Years)		BLASTING RECORDS	
Transfers/Succession of Operator	NA	Blasting Publication	NA
Temporary Cessation Notification	NA	Blasting Records (3 years)	NA
Reclamation Cost Estimate	X	ATFE Explosives Permit	NA
CERTIFICATIONS	_	Blasting Variances	NA
Pond Certifications	NA	Pre-Blast Surveys	NA
Annual Certifications for Impoundments	NA		
Fill Certifications for Excess Spoil	NA	ADDITIONAL RECORDS	
or Underground Development Waste	1,12	(specify)	
Quarterly Inspections	NA		
Compaction Testing	NA		
• Final Certification	NA		
Coal Processing Waste Banks	NA		
Haul Road Certifications	NA		
Access Road Certifications	NA		
100000 Road Confidentions	1111		
COMMENTS:			

Number of <u>Partial</u> Inspection this Fiscal Year: 0 Number of <u>Complete</u> Inspections this Fiscal Year: 1