Public Meeting held March 29, 2014 Lyons, CO

To discuss preliminary Analysis of the Little Thompson River Watershed and Big Elk Meadows Dams during the September 2013 Flooding



Willow Lake: Normal Storage: 26.7 acre-ft Surface Area: 5.5 acres Flood Storage: 60 acre-ft Order of Failure: 2 (12:02 p.m, 9/12)

Rainbow Lake: Normal Storage: 37.3 acre-ft Surface Area: 6.5 acres Flood Storage: 49 acre-ft Order of Failure: 3 (12:24 p.m, 9/12)

Mirror Lake: Normal Storage: 18.2 acre-ft Surface Area: 4 acres Flood Storage: 30 acre-ft Order of Failure: 5 (apprx. 2:00 a.m, 9/13)

Sunset Lake: Normal Storage: 11.4 acre-ft Surface Area: 2.5 acres Flood Storage: 19.3 acre-ft Order of Failure: 1 (7:41 a.m, 9/12) Meadow Lake: Normal Storage: 32.2 acre-ft Surface Area: 7 acres Flood Storage: 90.4 acre-ft Order of Failure: 4 (1:40 p.m, 9/12)

test for the transor ave

Big Elk Meadows Vicinity Map

CR 41



LITTLE THOMPSON RIVER WATERSHED SEPTEMBER 2013 STORM RAINFALL



















Willow Dam failing around the left end 9/12/13





Meadow Lake Dam during failure 9/12/13 @ 1:40pm



Meadow Lake Dam during failure 9/12/13 @ 1:40pm